



## Hard Water Bullet Cleaning And Re-assembly Instructions

Cleaning vinegar can be used to remove the green scale from the bullet core. Cleaning vinegar is a special vinegar and can be purchased at a local grocery store. Simply pour enough undiluted vinegar into a bowl so that the core is completely immersed and allow to soak for about an hour, remove and brush with a plastic bristle brush. Repeat this process until the core is clean.





Cleaning the conditioners core every few months (Possibly more often if you have high iron in your water) will ensure that the conditioner will work at it's peak performance. It's important to install the core with the beveled end on the water inlet end of the housing, This is because a venturi effect is created when the water enters the cores beveled end .

For questions or replacement parts, call Filter Water Direct at 316-640-2237 or see our website at

**[www.filterwaterdirect.com](http://www.filterwaterdirect.com)**